

BOC Gases Site Services		SAFETY SHARE	
Date/Time...	25-10-18	Detail any actions taken...	Safety share sent to H&S Office 25-10-18 I have uncoiled the hose and left it in a safe condition (see attached photos)
Location...	Engineering Dept Trumpington Street		
Reported by...	Graham Jack		
Safety Share No...	5		
Issue raised...	Hose tail Coiled under tension	Recommendations...	I will remind customers if they are disconnecting cylinders they must leave all aspects of the cylinder, regulator and pipework in a safe condition.
Risk rating...	LOW MEDIUM HIGH LOW		
Reported to...	Gary Steel		
Review Time	1 Day		
Further details...	A disconnected hose tail was left coiled under strain against a cylinder in a walk way. There was a potential risk the hose tail could uncoil at speed whipping anyone walking past at head height. (see attached photos)		
Customer Response:			
The Group Leader will raised this in the group meeting, to ensure that everyone knows that hose tails must not be coiled under tension.			

